

## Error statistics for the gearbox in drive trains of WEC

Dipl.-Ing. Jürgen Holzmüller

8.2 Ingenieurbüro Holzmüller Aurich, Julianenburger Straße 19a, D - 26605 Aurich


Since 2004, the experts of the 8.2-group ([www.8p2.de](http://www.8p2.de)) executed more than 170 visual inspections of gearboxes by video endoscope and more than 190 analyses of drive trains of megawatt turbines by offline vibration measurement. Out of those 80 turbines were examined combining both methods at the same time. So the results of the vibration measurements were evaluated / verified by the endoscope inspection and vice versa, what makes the 8.2 technology one of the most reliable in this field. So the customer receives reliable information of the condition of the gearbox. The combination of both, the visual and the acoustic method give the best impression of the condition and a base for further decisions of maintenance.

The lecture will give an overview of the so far received results and will show detailed pictures and graphics of 3 to 5 exemplary cases to compare and comment both detection methods.

Results video endoscope:



Results vibration analysis:



Statistic analysis of the examined gearboxes show following incidence of loss at gearboxes:

Manufacturer gearbox	Type of gearbox	Number of examined boxes	Videoendoscope	Bearing damages planetary stage	Gear damages planetary stage	Bearing damages spur stage	Gear damages spur stage	Vibration analysis	Bearing damages planetary stage	Gear damages planetary stage	Bearing damages spur stage	Gear damages spur stage	Miscellaneous
A	AA	N1	N11	...%	...%	...%	...%	N21	...%	...%	...%	...%	...%
	AB	N2	N12	...%	...%	...%	...%	N22	...%	...%	...%	...%	...%
B	BA	N3	N13	...%	...%	...%	...%	N23	...%	...%	...%	...%	...%
	BB	N4	N14	...%	...%	...%	...%	N24	...%	...%	...%	...%	...%
...	...	NX	N1X	...%	...%	...%	...%	N2X	...%	...%	...%	...%	...%
$\Sigma$			170	...%	...%	...%	...%	190	...%	...%	...%	...%	...%

Remarks: For matters of secrecy the gearboxes are not named by type and manufacturer.

The actual results will be available in the lecture.

## Error statistics for the gearbox in drive trains of WEC

by Jürgen Holzmüller, 8.2 Office Aurich

8.2

Error statistics for the gearbox in drive trains of WEC

[www.8p2.de](http://www.8p2.de)

8.2-Group



Technical experts  
at present 11 offices  
since 1995  
more than 8.000  
technical inspections  
independent technical  
expertises



Reliability

Cost efficiency

8.2

Error statistics for the gearbox in drive trains of WEC

[www.8p2.de](http://www.8p2.de)

## Methode of inspection



Inspection of  
gearboxes  
through available  
inspection apertures

## Methode of inspection



Listening of  
drive train  
with electronic  
stethoscope

06.03.2007

by Jürgen Holzmüller

5

## Methode of inspection



Vibration analysis  
of drive drain

Offline-Measurement  
8-channel  
additional rpm-signal

06.03.2007

by Jürgen Holzmüller

6

## Methode of inspection



Videoendoscopy  
of  
Gearbox

06.03.2007

by Jürgen Holzmüller

7

## Reasons for inspection



Technical inspections before  
end of guarantee  
Technical inspections to  
detect actual condition  
Damage expertise  
Expertise for court cases  
Value assessment

06.03.2007

by Jürgen Holzmüller

8

## Categories of damage



o.k.

Observation

Warning

Alarm

06.03.2007

by Jürgen Holzmüller

9

## Data base



Data Base of the following summary tables:

- 417 reports
- $P \geq 1.000 \text{ kW}$
- 3-stage gear boxes  
(1 planetary / 2 spur gear)
- since 1998

## Summary table I


Inspection method category	Visual inspection & Stethos.				Endoscopy				Vibration analysis			
	Obs.	Warn.	Alarm	$\Sigma$	Obs.	Warn.	Alarm	$\Sigma$	Obs.	Warn.	Alarm	$\Sigma$
Gearbox generally	9%	5%	0%	14%	1%	1%	3%	5%	1%	0%	0%	1%
Planetary stage	1%	0%	0%	1%	31%	9%	7%	47%	6%	3%	0%	9%
Plan. stage bearing					28%	21%	11%	60%	6%	2%	1%	9%
Plan. stage teeth					32%	14%	1%	47%				
LSS bearing	1%	0%	0%	1%	33%	8%	5%	46%	5%	1%	1%	7%
LSS teeth	25%	3%	0%	28%	23%	7%	3%	33%	6%	1%	0%	7%
MSS bearing	0%	0%	0%	0%	22%	7%	4%	33%	20%	7%	2%	29%
MSS teeth	21%	3%	0%	24%	27%	8%	4%	39%	16%	1%	0%	17%
HSS bearing	8%	7%	0%	15%	38%	9%	13%	60%	30%	12%	8%	50%
HSS teeth	29%	3%	0%	32%	22%	3%	4%	29%	23%	5%	1%	29%

06.03.2007

by Jürgen Holzmüller

11

## Exemplary Case 1: bearing damage



### Damage of outer ring / LSS

Visual inspection & Stethoscope: no indication of damage



Videoendoscopy: damage of category 'Warning'



vibration analysis : damage of category 'Warning'




06.03.2007

by Jürgen Holzmüller

12

## Exemplary Case 2: bearing damage



### Damage of inner ring / bearing MSS

Visual inspection & Stethoscope: no indication of damage



Videoendoscopy: no access to the bearing



vibration analysis : damage of category 'Warning'




06.03.2007

by Jürgen Holzmüller

13

## Exemplary Case 3: bearing damage



### Damage at planetary wheel

Visual inspection & Stethoscope: no access to the bearing



Videoendoscopy: damage of category 'Alarm'



vibration analysis: no indication of damage



06.03.2007

by Jürgen Holzmüller

14

## Summary table I



Inspection method category	Visual inspection & Stethos.				Endoscopy				Vibration analysis			
	Obs.	Warn.	Alarm	$\Sigma$	Obs.	Warn.	Alarm	$\Sigma$	Obs.	Warn.	Alarm	$\Sigma$
Gearbox generally	9%	5%	0%	14%	1%	1%	3%	5%	1%	0%	0%	1%
Planetary stage	1%	0%	0%	1%	31%	9%	7%	47%	6%	3%	0%	9%
Plan. stage bearing					28%	21%	11%	60%	32%	14%	1%	47%
Plan. stage teeth												
LSS bearing	1%	0%	0%	1%	33%	8%	5%	46%	5%	1%	1%	7%
LSS teeth	25%	3%	0%	28%	23%	7%	3%	33%	6%	1%	0%	7%
MSS bearing	0%	0%	0%	0%	22%	7%	4%	33%	20%	7%	2%	29%
MSS teeth	21%	3%	0%	24%	27%	8%	4%	39%	16%	1%	0%	17%
HSS bearing	8%	7%	0%	15%	38%	9%	13%	60%	30%	12%	8%	50%
HSS teeth	29%	3%	0%	32%	22%	3%	4%	29%	23%	5%	1%	29%

06.03.2007

by Jürgen Holzmüller

15

## Exemplary Case 4: gear damage



### Damage at gear planet wheel

Visual inspection & Stethoscope: no access



Videoendoscopy: damage of category 'Alarm'



vibration analysis : not ordered




06.03.2007

by Jürgen Holzmüller

16

## Exemplary Case 5: gear damage



## **Damage at gear / HSS**

Visual inspection & Stethoscope: damage of category ,Warning'

Videoendoscopy: damage of category 'Warning'

vibration analysis : no indication of damage

06.03.2007

17

## Summary table II

Manufacturer of gearbox	Type of gearbox	Bearing planetary carrier	Bearing planetary wheel	Teeth ring gear	Teeth planet & sun wheel	Bearing spur stage LSS	Bearing spur stage MSS	Bearing spur stage HSS	Teeth spur stage
A	I	0%	0%	0%	20%	0%	0%	0%	0%
A	II	0%	9%	21%	17%	14%	4%	33%	17%
A	II*	0%	0%	0%	12%	0%	0%	0%	0%
B	III	0%	17%	14%	12%	6%	3%	21%	3%
B	III*	0%	0%	0%	21%	0%	9%	10%	0%
B	IV	0%	0%	0%	11%	43%	0%	0%	0%
C	V	11%	9%	0%	14%	0%	10%	67%	22%
D	VI	0%	0%	22%	11%	0%	0%	13%	28%
E	VII	0%	0%	5%	0%	0%	0%	19%	6%
E	VIII	0%	41%	12%	0%	0%	0%	26%	0%
F	IX	0%	0%	0%	15%	0%	0%	0%	0%
Ø		1,0%	6,9%	6,7%	12,1%	5,7%	2,4%	17,1%	6,9%

## Summary table II

Manufacturer of gearbox	Type of gearbox	Bearing planetary carrier	Bearing planetary wheel	Teeth ring gear	Teeth planet & sun wheel	Bearing spur stage LSS	Bearing spur stage MSS	Bearing spur stage HSS	Teeth spur stage
A	I	0%	0%	0%	20%	0%	0%	0%	0%
A	II	0%	9%	21%	17%	14%	4%	33%	17%
A	II*	0%	0%	0%	12%	0%	0%	0%	0%
B	III	0%	17%	14%	12%	6%	3%	21%	3%
B	III*	0%	0%	0%	21%	0%	9%	10%	0%
B	IV	0%	0%	0%	11%	43%	0%	0%	0%
C	V	11%	9%	0%	14%	0%	10%	67%	22%
D	VI	0%	0%	22%	11%	0%	0%	13%	28%
E	VII	0%	0%	5%	0%	0%	0%	19%	6%
E	VIII	0%	41%	12%	0%	0%	0%	26%	0%
F	IX	0%	0%	0%	15%	0%	0%	0%	0%
Ø		1,0%	6,9%	6,7%	12,1%	5,7%	2,4%	17,1%	6,9%

## Summary table II

Manufacturer of gearbox	Type of gearbox	Bearing planetary carrier	Bearing planetary wheel	Teeth ring gear	Teeth planet & sun wheel	Bearing spur stage LSS	Bearing spur stage MSS	Bearing spur stage HSS	Teeth spur stage
A	I	0%	0%	0%	20%	0%	0%	0%	0%
A	II	0%	9%	21%	17%	14%	4%	33%	17%
A	II*	0%	0%	0%	12%	0%	0%	0%	0%
B	III	0%	17%	14%	12%	6%	3%	21%	3%
B	III*	0%	0%	0%	21%	0%	9%	10%	0%
B	IV	0%	0%	0%	11%	43%	0%	0%	0%
C	V	11%	9%	0%	14%	0%	10%	67%	22%
D	VI	0%	0%	22%	11%	0%	0%	13%	28%
E	VII	0%	0%	5%	0%	0%	0%	19%	6%
E	VIII	0%	41%	12%	0%	0%	0%	26%	0%
F	IX	0%	0%	0%	15%	0%	0%	0%	0%
Ø		1,0%	6,9%	6,7%	12,1%	5,7%	2,4%	17,1%	6,9%

## Summary table II

Manufacturer of gearbox	Type of gearbox	Bearing planetary carrier	Bearing planetary wheel	Teeth ring gear	Teeth planet & sun wheel	Bearing spur stage LSS	Bearing spur stage MSS	Bearing spur stage HSS	Teeth spur stage
A	I	0%	0%	0%	20%	0%	0%	0%	0%
A	II	0%	9%	21%	17%	14%	4%	33%	17%
A	II*	0%	0%	0%	12%	0%	0%	0%	0%
B	III	0%	17%	14%	12%	6%	3%	21%	3%
B	III*	0%	0%	0%	21%	0%	9%	10%	0%
B	IV	0%	0%	0%	11%	43%	0%	0%	0%
C	V	11%	9%	0%	14%	0%	10%	67%	22%
D	VI	0%	0%	22%	11%	0%	0%	13%	28%
E	VII	0%	0%	5%	0%	0%	0%	19%	6%
E	VIII	0%	41%	12%	0%	0%	0%	26%	0%
F	IX	0%	0%	0%	15%	0%	0%	0%	0%
Ø		1,0%	6,9%	6,7%	12,1%	5,7%	2,4%	17,1%	6,9%

## Summary

- Results are depending on inspection method
- First indications of reliability increase can be observed
- Damage causes have to be investigated further
- Retrofits have to include improvements



Thank you  
for your  
attention



Wir bedanken uns  
für Ihre Aufmerksamkeit